





POLYMAX[®] 11M


a	11mm
b	7mm



a	24.4mm
b	7.0mm
p	13.2mm



a	37.6mm
b	7.0mm
p	13.2mm

11M					
Part Number	Ribs				
	1	2	3	4	5
11 M 710	○	○	○		
11 M 730	○	○	○		
11 M 750	○	○	○		
11 M 775	○	○	○		
11 M 800	○	○	○		
11 M 825	○	○	○		
11 M 850	○	○	○		
11 M 875	○	○	○		
11 M 900	○	○	○		
11 M 925	○	○	○		
11 M 950	○	○	○		
11 M 975	○	○	○		
11 M 1000	○	○	○		
11 M 1030	○	○	○		
11 M 1060	○	○	○		
11 M 1090	○	○	○		
11 M 1120	○	○	○		
11 M 1150	○	○	○		
11 M 1180	○	○	○		
11 M 1220	○	○	○		
11 M 1250	○	○	○		
11 M 1280	○	○	○		
11 M 1320	○	○	○		
11 M 1360	○	○	○		
11 M 1400	○	○	○		
11 M 1450	○	○	○		
11 M 1500	○	○	○		
11 M 1550	○	○	○		
11 M 1600	○	○	○		
11 M 1650	○	○	○		
11 M 1700	○	○	○		
11 M 1750	○	○	○		
11 M 1800	○	○	○		
11 M 1850	○	○	○		
11 M 1900	○	○	○		
11 M 1950	○	○	○		
11 M 2000	○	○	○		
11 M 2060	○	○	○		
11 M 2120	○	○	○		
11 M 2180	○	○	○		
11 M 2240	○	○	○		
11 M 2300	○	○	○		